San	nitized Copy /	Approved for F	Release 2011/	/05/31 : CIA-	RDP82-0045	57R00140019	90004-6 -	
Ou.		CE	NTRAL INTEL	LIGENCE AG	ENCY	REPORT		
		INFC	<b>FAMR</b>	<b>#</b>	THU	-		
							31	
COUNTRY	USSR			Faor	77 mar = 2 a a	DATE DISTR	R. 39 Me	rch 1948
SUBJECT	Aircreft	Factories		COM	FIDENTIAL	_NO. OF PAG	SES	
						1		
PLACE						YO. OF EN	CLS.	50V4 IIII
CQUIRED						LISTED BELOW		50X1-HU
DATE OF	II.							
THIS DOCUMENT OF THE UNITED S U. S. C., 21 AND 2 OF ITS CONTENTS HISITED BY LAW. EVER INFORMATIO	CONTAINS INFORMATION PRAYES WITHIN THE M PROPERTY OF THE MANY MANUER TO TREPRODUCTION OF CONTAINED IN BOI THE PROPERTY OF THE RECEIVE	A APPECTING THE MATION BANING OF THE ESPION TRAINSHISSION OR THE AN URBUTHORNEED PER THIS FORM IS PROMISION OF THE FORM MAY ING ASSECT.	IAL DEFENSE ALIGE ACT SO SE REVELATION SON IS PRO-TICD. HOW-TED. HOW-TED.			FORMATION INTELLIGENC	FOR THE	
1.	The facto	ry at Penza	(53°10°N,	45°@) whic	h produces	furniture	and repa	: <b>1</b> rs
1.	aircraft	is believed	(53°10°N, to be No.	163 rather	than No. 1	169. No. 1	63 forme	erly air-
	aircraft produced craft.	is <b>believ</b> ed undercarria	to be No .ges_and ek	163 rather is but is	than No. 1 now reports	169. No. 1 ed to be re	63 forme pairing	erly air 50X1-HU
2.	aircraft produced craft.  The ident	is <b>believ</b> ed undercarria	to be Nee!	163 rather is but is	than No. 1 now reports	169. No. 1 ed to be re	63 forme pairing	erly air- 50X1-HU as
2.	reaft.  The ident	is believed undercarria diffication of a correct.	to be No. ; ses and sk	169 rather is but is a	than No. 1 now reports aircraft f	169. No. 10 ed to be re-	63 forme pairing Saratov	erly air- 50X1-HU as 50X1-HUN
	produced craft.  The ident No. 292 i	is believed undercarria if: cation o s correct. Factory No.	to be No .ges_and ek	169 rather is but is a carrier in Zayod*	than No. 1 now reports aircraft f	169. No. 10 ed to be re-	63 forme pairing Saratov	erly air- 50X1-HU as 50X1-HUM
2.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl	is believed undercarria diffication of a correct. Factory No. y aircraft	to be No	163 rather is but is a saved*  (55°15'N, heretofore	than No. 1 now reports aircraft f	169. No. 10 de to be reparted	63 forme pairing Saratov to have	erly ear- 50X1-HU as 50X1-HUM pro- 50X1-HUI
2.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircraft be No. 16	is believed undercarria iffication of secorrect. Factory No., y aircraft aft factory 6, which fo	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing  Saratov  to have  believed  Factory	erly air- 50X1-HU as 50X1-HUM pro- 50X1-HUI
2.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircraft be No. 16	is believed undercarria iffication of secorrect. Factory No., y aircraft aft factory 6, which fo	f the "Komb 20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing  Saratov  to have  believed  Factory	erly air- 50X1-HU as 50X1-HUM pro- 50X1-HUI
2.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircraft be No. 16	is believed undercarria iffication of secorrect. Factory No., y aircraft aft factory 6, which fo	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing  Saratov  to have  believed  Factory	erly air- 50X1-HU as 50X1-HUM pro- 50X1-HUI
2.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircraft be No. 16	is believed undercarria iffication of secorrect. Factory No., y aircraft aft factory 6, which fo	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing  Saratov  to have  believed  Factory	50X1-HUM 50X1-HUM 50X1-HUM 50X1-HUM
2.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircraft be No. 16	is believed undercarria iffication of secorrect. Factory No., y aircraft aft factory 6, which fo	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing Saratov  to have believed Factory	arly air- 50X1-HU as 50X1-HUN 50X1-HU
2.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircraft be No. 16	is believed undercarria ification of a correct.  Factory No. y aircraft aft factory 6, which for a believed	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing Saratov  to have believed Factory	srly air 50X1-HU as 50X1-HUM pro- 50X1-HUM
2. 3. 4.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircraft be No. 16	is believed undercarria iffication of a correct.  Factory No. y aircraft aft factory 6, which for a believed	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing Saratov  to have believed Factory	50X1-HUM 50X1-HUM 50X1-HUM 50X1-HUM
2. 3. 4.	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircr be No. 164 i	is believed undercarria diffication of a correct.  Factory No. y aircraft aft factory 6, which for a believed	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing Saratov  to have believed Factory	50X1-HUM 50X1-HUM 50X1-HUM 50X1-HUM
2. 3. 4. Docume	aircraft produced craft.  The ident No. 292 i Aircraft duced onl  The aircraft duced No. 164 i	is believed undercarria iffication of a correct.  Factory No. y aircraft aft factory of, which for a believed asset is self-actional actions.	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing Saratov  to have believed Factory	50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUI
2. 3. 4. Docume No Cha	aircraft produced craft.  The ident No. 292 i Aircraft duced onl  The aircraft ho. 164 i	is believed undercarria iffication of a correct. Factory No. y aircraft aft factory 6, which for a believed	f the "Komb  20 at Omak components i	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is it. Aircraft	63 forme pairing Saratov  to have believed Factory	50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUI
2.  3.  4.  Docume No Cha	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircr be No. 164 i No. 164 i  CHASSIFIED DDA Memo	is believed undercarria iffication of a correct.  Factory No. y aircraft aft factory 6, which for shelieved  To: TS  1.4 / pr 77	to be No	163 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	l69. No. 10 dd to be reparted to 164 is 16. Aircraft	63 forme pairing Saratov  to have believed Factory	50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUI
Docume No Cha Class. Auth:	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircr be No. 164 i No. 164 i  ent No. ANGE in CULASSIFIED CHANCED DDA Memo DDA REC.	is believed undercarria iffication of a correct.  Factory No. y aircraft af: factory 6, which for a believed ass.   77/12/2	to be No	163 rather is but is but is but is a second of the second	than No. 1 now reports aircraft f  73°25'E) f  corted as N er aircraft	169. No. 10 ded to be reparted is reported in Aircraft 1, 48°28'E)	63 forme pairing Saratov  to have believed Factory	50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUI
2.  3.  4.  Docume No Cha	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircr be No. 164 i No. 164 i  ent No. ANGE in CULASSIFIED CHANCED DDA Memo DDA REC.	is believed undercarria iffication of a correct.  Factory No. y aircraft aft factory 6, which for shelieved  To: TS  1.4 / pr 77	to be No	163 rather is but is but is but is a second of the second	than No. 1 now reports aircraft f  73°25'E) f  rorted as N er aircraft an (53°19'N	169. No. 10 ded to be reparted is reported in Aircraft 1, 48°28'E)	63 forme pairing Saratov  to have believed Factory	50X1-HUM 50X1-HUM 50X1-HUM 50X1-HUM
Docume No Cha Class. Auth:	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircr be No. 164 i No. 164 i  ent No. ANGE in CULASSIFIED CHANCED DDA Memo DDA REC.	is believed undercarria iffication of a correct.  Factory No. y aircraft aft factory 6, which for a believed  70: TS  77/15/27  77 By	to be No	169 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f 73°25'E) f rorted as N er aircraft an (53°19'N	169. No. 10 ded to be reparted is reported is. Aircraft 1, 48°28'E)	63 forme pairing Saratov to have believed Factory	50X1-HUM 50X1-HUM 50X1-HUM 50X1-HUM
Docume No Cha Class. Auth:	aircraft produced craft.  The ident No. 292 i Aircraft duced onl The aircr be No. 164 i No. 164 i  ent No. ANGE in CULASSIFIED CHANCED DDA Memo DDA REC.	is believed undercarria iffication of a correct.  Factory No. y aircraft af: factory 6, which for a believed ass.   77/12/2	to be Neggines and skinges and skinges and skinges and skinges are onesk with the belocated by production be located by the belocated by the b	169 rather is but is a sure is but is a sure i	than No. 1 now reports aircraft f 73°25'E) f rorted as N er aircraft an (53°19'N	169. No. 10 ded to be reparted is reported in Aircraft 1, 48°28'E)	63 forme pairing Saratov to have believed Factory	50X1-HUM 50X1-HUM 50X1-HUM 50X1-HUM